

XPlotter G-code Specification

G-commands

G0 & G1: Linear Move

Usage

G0 Xnnn Ynnn Fnnn

G1 Xnnn Ynnn Fnnn

Parameters

Not all parameters need to be used, but at least one has to be used

Xnnn The position to move to on the X axis

Ynnn The position to move to on the Y axis

Fnnn The feedrate per minute of the move between the starting point and ending point

Examples

```
G0 X100 Y120.25 ; Move to 100mm on the X axis, and 120.25mm on the Y axis
G0 F2500 ; Set the feedrate to 2500mm/minute
```

G2 & G3: Controlled Arc Move

Usage

G2 Xnnn Ynnn Innn Jnnn Fnnn (Clockwise Arc)

G3 Xnnn Ynnn Innn Jnnn Fnnn (Counter-Clockwise Arc)

Parameters

Xnnn The position to move to on the X axis

Ynnn The position to move to on the Y axis

Innn The point in X space from the current X position to maintain a constant distance from

Jnnn The point in Y space from the current Y position to maintain a constant distance from

Fnnn The feedrate per minute of the move between the starting point and ending point

Examples

```
G2 X90.6 Y13.8 I5 J10 ; Move in a clockwise arc from the current point to point (X=90.6,
Y=13.8), with a center point at (X=current_X+5, Y=current_Y+10)
G3 X90.6 Y13.8 I5 J10 ; Move in a counter-clockwise arc from the current point to point
(X=90.6,Y=13.8), with a center point at (X=current_X+5,
Y=current_Y+10))
```

G4: Dwell

Pause the machine for a period of time.

Parameters

Pnnn Time to wait, in milliseconds

Snnn Time to wait, in seconds

Example

G4 P200 ; In this case sit still doing nothing for 200 milliseconds. "G4 S2" and "G4 P2000" are equivalent.

G20: Set Units to Inches

Units from now on are in inches.

G21: Set Units to Millimeters

Units from now on are in millimeters. (default)

G28: Move to Origin (Home)

Parameters

This command can be used without any additional parameters.

X Flag to go back to the X axis origin

Y Flag to go back to the Y axis origin

Examples

G28 ; Home all axes

G28 X ; Home the X axis

G90: Set to Absolute Positioning

All coordinates from now on are absolute relative to the origin of the machine. (default)

G91: Set to Relative Positioning

All coordinates from now on are relative to the last position.

G92: Set Position

Parameters

Xnnn new X axis position

Ynnn new Y axis position

Example

G92 X10 Y90 ; Allows programming of absolute zero point, by resetting the current position to the values specified. This would set the machine's X coordinate to 10, and the Y coordinate to 90. No physical motion will occur.

M-commands

M0: Disable Screen Touch

When control the machine through USB serial port, this command disable screen touch, so that you don't have to worry about wrong touch on the screen.

M1: Enable Screen Touch

Enable screen touch, so that you can use touch screen to control the machine again.

M2: Turn off LCD

Turn off LCD light.

M3: Set Laser Brightness

Set laser brightness. The protection mechanism makes the laser turn on only when the machine is moving.

Usage

M3 Snnn

Parameters

Snnn (0~255) 0 means zero brightness, 255 means full brightness

Examples

```
M3 S100 ; Set laser brightness to 100
M3 S255 ; Set laser brightness to 255
```

M4: Laser Focusing

Turn on laser at a relatively low brightness, so that you can adjust laser focusing.

M5: Laser Off

Turn off laser.

M10: Vacuum On

Turn on vacuum motor.

M11: Vacuum Off

Turn off vacuum motor.

M300: Set Servo Angle

Set pen holder's servo motor angle to change the height of pen holder.

Usage

M300 Snnn

Parameters

Snnn (0~180) angle of the servo, Unit: Degree

Examples

M3 S100 ; Set servo angle to 100 degree

M3 S160 ; Set servo angle to 160 degree

Serial Port Parameters

baudrate	115200
parity	none
data bits	8
stop bits	1

Notice!

1. Every command should end with one byte char `\n` (Line Feed) or `\r` (Carriage Return)
2. After command received, an "ok" feedback from the machine end with char `\n`